

## ENERGY SAVER GLOBE – MERCURY EXPOSURE

What happened.

On the 10<sup>th</sup> February 2011 the energy saver globe fused at the home of the IP. He did not wait for the globe to cool down, standing on a chair with a piece of cloth and remove the energy saver globe. Due to the heat of the energy saver globe he dropped the globe. As the globe fell on the floor it “explode” (brake). As he descend from the chair he stepped into the broken glass and exposed mercury powder.


The IP was admitted to hospital for treatment of the cuts. He spent two weeks in ICU and at one stage it was feared that his foot need to be amputated. Currently his foot is connected to a vacuum pump to remove continuously dead tissue. Long road of recovery is awaiting him.



# ENERGY SAVER GLOBE – MERCURY EXPOSURE



## ENERGY SAVER GLOBE – MERCURY EXPOSURE



Vacuum Pump Connected to remove dead tissue from the foot.